

Photographs – Exhibit TJFA 424

Exhibit TJFA 424-A, Joint Set in Weathered Taylor Marl – Skyline MSW Landfill



Exhibit TJFA 424-B, Mineralization in Joint in Weathered Taylor Marl – Skyline MSW Landfill



Photographs – Exhibit TJFA 424

Exhibit TJFA 424-C, Intersecting Joints in Weathered Taylor Marl – Skyline MSW Landfill



Photographs – Exhibit TJFA 424

Exhibit TJFA 424-D, Excavation Slope Failure – Skyline MSW Landfill, 1999



Exhibit TJFA 424-E, Excavation Slope Failure – Skyline MSW Landfill, 1999



Photographs – Exhibit TJFA 424

Exhibit TJFA 424-F, Excavation Slope Failure – Skyline MSW Landfill, 1999



Exhibit TJFA 424-G, Excavation Slope Failure – Skyline MSW Landfill, 1999



Photographs – Exhibit TJFA 424

Exhibit TJFA 424-H, Excavation Slope Failure – City of Irving MSW Landfill, 1999



*Photograph courtesy of Dr. Timothy D. Stark, P.E., University of Illinois

Exhibit TJFA 424-I, Excavation Slope Failure – City of Irving MSW Landfill, 1999



Photographs – Exhibit TJFA 424

Exhibit TJFA 424-J, Excavation Slope Failure – City of Irving MSW Landfill, 1999



Exhibit TJFA 424-K, Excavation Slope Failure – City of Irving MSW Landfill, 1999

