



A “tension crack” on the north side of the IWU at the top of the slope.